

WATER-COOLED TRANSMISSION COOLERS

17- 3- 1012-B	S/W REPLACEMENT	17- 3- 1277-D	S/W REPLACEMENT
17- 3- 1013-A	S/W REPLACEMENT	17- 3- 1279-A	S/W REPLACEMENT
17- 3- 1013-B	S/W REPLACEMENT	17- 3- 1279-B	S/W REPLACEMENT
17- 3- 1013-C	S/W REPLACEMENT	17- 3- 1279-C	S/W REPLACEMENT
17- 3- 1016-A	S/W REPLACEMENT	17- 3- 1281-A	S/W REPLACEMENT
17- 3- 1040-A	S/W REPLACEMENT	17- 3- 1281-D	S/W REPLACEMENT
17- 3- 1043-A	S/W REPLACEMENT	17- 3- 1283	S/W REPLACEMENT
17- 3- 1043-B	S/W REPLACEMENT	17- 3- 1284-A	S/W REPLACEMENT
17- 3- 1069-A	S/W REPLACEMENT	17- 3- 1286-A	S/W REPLACEMENT
17- 3- 1103-A	S/W REPLACEMENT	17- 3- 1288-A	S/W REPLACEMENT
17- 3- 1105-A	S/W REPLACEMENT	17- 3- 1335-A	S/W REPLACEMENT
17- 3- 1127-A	S/W REPLACEMENT	17- 3- 1545	S/W REPLACEMENT
17- 3- 1176-A	S/W REPLACEMENT	17- 3- 2243	S/W REPLACEMENT
17- 3- 1178-A	S/W REPLACEMENT	17- 3- 3058-A	S/W REPLACEMENT
17- 3- 1179-B	S/W REPLACEMENT	17- 3- 3101-3C	S/W REPLACEMENT
17- 3- 1184-B	S/W REPLACEMENT	17- 3- 3141-A	S/W REPLACEMENT
17- 3- 1192-A	S/W REPLACEMENT	17- 3- 10103-A	S/W REPLACEMENT
17- 3- 1203-A	S/W REPLACEMENT	17- 4- 1004-A	S/W REPLACEMENT
17- 3- 1222-A	S/W REPLACEMENT	17- 4- 1023-B	S/W REPLACEMENT
17- 3- 1226-A	S/W REPLACEMENT	17- N- 21779	SPARTAN REPLACEMENT
17- 3- 1226-C	S/W REPLACEMENT	17- 232599	S/W REPLACEMENT
17- 3- 1233-A	S/W REPLACEMENT	17- 1207950	S/W REPLACEMENT
17- 3- 1234-A	S/W REPLACEMENT	17- 12414334	REPLACEMENT COOLER
17- 3- 1246-A	S/W REPLACEMENT	17- 3024297	S/W REPLACEMENT
17- 3- 1249-B	S/W REPLACEMENT	17- 3320342	S/W REPLACEMENT
17- 3- 1249-C	S/W REPLACEMENT	17- 5586644	EATON REPLACEMENT
17- 3- 1249-D	S/W REPLACEMENT	17- 5586654	EATON REPLACEMENT
17- 3- 1249-G	S/W REPLACEMENT	17- 29500137	ALLISON REPLACEMENT
17- 3- 1249-T	S/W REPLACEMENT	17- 29500166	ALLISON REPLACEMENT
17- 3- 1255-A	S/W REPLACEMENT	17- 29500669	ALLISON REPLACEMENT
17- 3- 1255-S	S/W REPLACEMENT	17- 29511824	ALLISON REPLACEMENT
17- 3- 1259-A	S/W REPLACEMENT	17- 29511835	ALLISON REPLACEMENT
17- 3- 1259-B	S/W REPLACEMENT	17- 29523124	ALLISON REPLACEMENT
17- 3- 1261-A	S/W REPLACEMENT	17- 0287-FF2	REPLACEMENT COOLER
17- 3- 1261-B	S/W REPLACEMENT	17- 1126859-C1	IH REPLACEMENT
17- 3- 1262-B	S/W REPLACEMENT	17- 1266994-H91	IH REPLACEMENT
17- 3- 1263-A	S/W REPLACEMENT	17- 1498-442-00	SPARTAN REPLACEMENT
17- 3- 1270-A	S/W REPLACEMENT	17- 1498-FF2-00	SPARTAN REPLACEMENT
17- 3- 1270-B	S/W REPLACEMENT	17- 1701-FF2-00	SPARTAN REPLACEMENT
17- 3- 1273-A	S/W REPLACEMENT	17- 43-2036	CHAMPION REPLACEMENT
17- 3- 1274-A	S/W REPLACEMENT	17- 62-1427DL	IH REPLACEMENT
17- 3- 1274-B	S/W REPLACEMENT	17- 62-8600	IH REPLACEMENT
17- 3- 1274-C	S/W REPLACEMENT	17- G1004790	REPLACEMENT COOLER